



Instrument Engineering Change Notice

NO. TEC6-2205

Sakura Finetek Japan Co. Ltd.

PRODUCT NAME : Tissue-Tek TEC6 DATE : July 29, 2022
PRODUCT CODES : All models ORIGINATOR : SSCL R&D/Mate.Mag.
IECN TYPE : PART NUMBER CHANGE REFERENCE NUMBER : See the attached list
SERIAL NUMBERS AFFECTED : See the attached list ATTACHMENTS : TEC6-2205_PARTS CHANGE LIST
FIELD RETROFIT REQUIRED : NO

Title: Part Number Change

[REASON AND DESCRIPTION FOR CHANGE]

The part numbers of the parts for the instrument were changed as mentioned in the Parts Change List attached.
The interchangeability of the parts is YES, and the inventory disposal is NO.

[PART CHANGE] (IVDP=Inventory Disposal, ICHB=Inter Changeable)

| Description | Old | QTY | IVDP | New | QTY | ICHB |
|---------------------------|-----|-----|------|-----|-----|------|
| **See the attached list** | --- | --- | NO | --- | --- | YES |

[REMARKS]

See the attached list.

[DISTRIBUTION]

[APPROVAL]

- SFA
- SFJ
- SFE
- SCN

Name : T. Sugawara

Signature :

Part Number Change List

| IECN No. | Product Name | Ref Number | Part Name | Old/Incorrect | New/Correct | First Production | First Production Lot & S/N affected | | | | | | Reason Description |
|-----------|--------------|------------|--|------------------|------------------|------------------|-------------------------------------|------|------------------------|------------------------|------------|------|---|
| | | | | | | | Model Lot1 | Lot1 | Model Lot2 | Lot2 | Model Lot3 | Lot3 | |
| TEC6-2205 | TEC6 CM | 17102 | Power Cord | A4010535 | 00001-4038 | 6-2021 | N/A | N/A | 5117, 5129 | 0151, 0127 | 5113 | 0396 | Discontinuation of current power cord (for 200V system only) |
| TEC6-2205 | TEC6 CM | 20442 | Power Distribution Board | A-MAL3-0201-01-A | A-MAL3-0201-02-A | 5-2022 | 5109 | 0848 | 5105, 5117, 5129 | 0412, 0247, 0194 | 5113 | 0563 | Added holes for wiring to make the part usable in common to new "KS2" model |
| TEC6-2205 | TEC6 EM | 16737 | HP.Forceps Holder Unit (100/115V) | --- | A-MAL2-U020-00-A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | (For maintenance only) Added new replacement component for convenience in replacement of hot plate unit and forceps holder unit |
| TEC6-2205 | TEC6 EM | 16737 | HP.Forceps Holder Unit (230V) | --- | A-MAL2-U021-00-A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | (For maintenance only) Added new replacement component for convenience in replacement of hot plate unit and forceps holder unit |
| TEC6-2205 | TEC6 EM | 17101 | Power Cord | A4010534 | 00001-4037 | 2-2021 | N/A | N/A | 5116, 5128 | 0122, 0123 | 5112 | 0344 | Discontinuation of current power cord (for 200V system only) |
| TEC6-2205 | TEC6 EM | 20300-1 | Heat-insulation Backing Material for Hot Plate | A-MAL2-0150-00-A | A-MAL2-0150-01-A | 12-2021 | 5108 | 0757 | 5104, 5116, 5128 | 0364, 0182, 0153 | 5112 | 0477 | Updated drawing number by adding alternative adhesive tape to drawing because of difficulty procuring current adhesive tape |
| TEC6-2205 | TEC6 EM | 20300-1 | Heat-insulation Backing Material (2) for Hot Plate | A-MAL2-0151-00-A | A-MAL2-0151-01-A | 12-2021 | 5108 | 0757 | 5104, 5116, 5128 | 0364, 0182, 0153 | 5112 | 0477 | Updated drawing number by adding alternative adhesive tape to drawing because of difficulty procuring current adhesive tape |