



# Instrument Engineering Change Notice

NO. Prisma Plus-2008

Sakura Finetek Japan Co. Ltd.

PRODUCT NAME : Tissue-Tek Prisma Plus      DATE : October 19, 2020  
PRODUCT CODES : 6170, 6171, 6172, 6173,      ORIGINATOR : Takamura  
6174, 6175, 6177      REFERENCE NUMBER : 16859-1, 16994,  
IECN TYPE : Part Design Change      17014, 17063  
SERIAL NUMBERS AFFECTED : See Remarks      ATTACHMENTS : AK6-QE-057-01  
FIELD RETROFIT REQUIRED : NO      Replacement  
Instructions for New  
Oil Damper Unit

## Title: Change of Oil Damper

### [ REASON AND DESCRIPTION FOR CHANGE ]

Due to product discontinuation, the oil damper for opening and closing the loading door is to be replaced with the new one.

Because the new oil damper is not interchangeable with the old damper and needs to be installed in a different way, the parts peripheral to the oil damper are also redesigned.

For convenience in replacement of the old oil damper, the oil damper replacement kit is available as a maintenance part.

For details, refer to the attached document "AK6-QE-057-01 Replacement Instructions for New Oil Damper Unit".

### [ PART CHANGE ] ( IVDP=Inventory Disposal, ICHB=Inter Changeable )

Description	Old	QTY	IVDP	New	QTY	ICHB
Oil Damper / B-466-3	D9280283	1	NO	---	---	NO
Oil Damper / B-499-3	---	---		00001-3531	1	NO
Damper Installation Plate	K24-227-01	1	NO	---	---	NO
Door Damper Mounting Frame	---	---		A-MK25-0140-01-A	1	NO
Door Damper Stay	K24-116-00	1	NO	A-MK25-0143-00-A	1	NO
Door Damper Stay A	---	---		A-MK25-0146-00-A	1	NO
Damper Shaft	K24-125-00	1	NO	---	---	NO
Flange Bearing / JFM-0608-06	---	---		00001-3484	2	
Plastic Washer / PPSW6	---	---		00001-3532	2	
Oil Damper Replacement Kit	---	---		A-MK25-U023-00-A	1	

**[ REMARKS ]**

Implementation:

AD/AS: K.D.

ED: 6172 0198 and after

ES: 6173 0299 and after

JD: 6174 0286 and after

JS: 6175 0069 and after

JCS: 6177 0196 and after

---

**[ DISTRIBUTION ]**

SFA

SFJ

SFE

SCN

**[ APPROVAL ]**

Name : T. Sugawara

Signature :

